


FIG. 1
(PRIOR ART)







FIG. 3






FIG. 5




FIG. 6





FIG. 7

FIG. 8

136

138

DESCRIPTION	VALUE	UNITS
OXYGEN SENSOR	1196	MV
TEMP	1320	DEG F
% CO	1.0	PERCENT
ACTIVITY OF CARBON A _C	.97	
PROCESS SET POINT A _C	1.0	

140

The diagram shows a control panel (136) with a data table (138) and four indicator lights (140) at the bottom. The table lists various process parameters and their current values and units.

DESCRIPTION	VALUE	UNITS
OXYGEN SENSOR	1196	MV
TEMP	1320	DEG F
% CO	1.0	PERCENT
ACTIVITY OF CARBON A _C	.97	
PROCESS SET POINT A _C	1.0	